

Motorsport 2011_Price List <Release: CGM110101.01>

Service and Repair

※消費税は別途申し受けます。

Old Code	New Code	Description	標準価格 (税抜き)
<u>SERVICINGS – WHEEL GUNS</u>		<u>Service & Repair</u>	
RMH4000		DP 4000 Service & Repair	¥116,300
RMH3000	R.01.01.01.0019	DP 3000 Service & Repair	¥106,000
RMH2000	R.01.01.01.0001	DP 2000-S Service & Repair	¥76,300
RMH2000	R.01.01.01.0001	DP 2000 Service & Repair	¥76,300
RMH191192	R.01.01.01.0013	DP 192 Service & Repair	¥95,200
RMH196S197S	R.01.01.01.0009	DP 197-SF Service & Repair	¥76,300
RMH196S197S	R.01.01.01.0009	DP 197-S Service & Repair	¥76,300
RMH196197	R.01.01.01.0011	DP 197 Service & Repair	¥76,300
RMH196S197S	R.01.01.01.0009	DP 196-S Service & Repair	¥76,300
RMH196197	R.01.01.01.0011	DP 196 Service & Repair	¥76,300
RMH176	R.01.01.01.0007	DP 176 S.F. Service & Repair	¥55,800
RMH34	R.01.01.01.0005	DP 34 S.F. Service & Repair	¥44,200
RMH30	R.01.01.01.0003	DP 30 S.F. Service & Repair	¥44,200
RMH36	R.01.01.01.0021	DP 36-SF Service & Repair	¥41,900
		<u>Service, Repair & Repaint</u>	
RMHV4000		DP 4000 Service, Repair & Repaint	¥135,300
RMHV3000	R.01.01.01.0020	DP 3000 Service, Repair & Repaint	¥124,900
RMHV2000	R.01.01.01.0002	DP 2000-S Service, Repair & Repaint	¥89,500
RMHV2000	R.01.01.01.0002	DP 2000 Service, Repair & Repaint	¥89,500
RMHV191192	R.01.01.01.0014	DP 192 Service, Repair & Repaint	¥103,300
RMHV196S197S	R.01.01.01.0010	DP 197-SF Service, Repair & Repaint	¥89,500
RMHV196S197S	R.01.01.01.0010	DP 197-S Service, Repair & Repaint	¥89,500
RMHV196197	R.01.01.01.0012	DP 197 Service, Repair & Repaint	¥89,500
RMHV196S197S	R.01.01.01.0010	DP 196-S Service, Repair & Repaint	¥89,500
RMHV196197	R.01.01.01.0012	DP 196 Service, Repair & Repaint	¥89,500
RMHV176	R.01.01.01.0008	DP 176 S.F. Service, Repair & Repaint	¥65,400
RMHV34	R.01.01.01.0006	DP 34 S.F. Service, Repair & Repaint	¥55,800
RMHV30	R.01.01.01.0004	DP 30 S.F. Service, Repair & Repaint	¥55,800
RMHV36	R.01.01.01.0022	DP 36-SF Service, Repair & Repaint	¥53,000
		<u>Service, Repair & Upgrade</u>	
CONV2000S	R.02.01.01.0013	DP 2000 Service, Repair & Upgrade to DP 2000-S	¥195,700
	R.02.01.01.0023	DP 3000 – DP 2000-S Ceramics Bearings Upgrade	¥87,000

Motorsport 2011_Price List <Release: CGM110101.01>

Service and Repair

※消費税は別途申し受けます。

Old Code	New Code	Description	標準価格 (税抜き)
<u>SERVICINGS – AIR PRESSURE REGULATOR</u>			
RMHR1100HCQ	R.01.03.0001	RGPRSF1 Service & Repair	¥31,200
RMHR1100HDQ	R.01.03.0002	RGPRSF2 Service & Repair	¥31,200
RMHR1200HDQ	R.01.03.0003	RGPRSF4 Service & Repair	¥31,200
		RGPRSF6 Service & Repair	¥31,200
		RGPRSF7 Service & Repair	¥31,200
RMHR1100HCQ	R.01.03.0008	RGPRSF1 with glycerin gauge Service & Repair	¥33,800
RMHR1100HDQ	R.01.03.0010	RGPRSF2 with glycerin gauge Service & Repair	¥33,800
RMHR1200HDQ	R.01.03.0009	RGPRSF4 with glycerin gauge Service & Repair	¥33,800

※標準交換部品以外のパーツに損傷、消耗等が有り交換が必要な場合は別途請求になります。

※荷造り運賃、輸出入手数料を含む。

《年に1度、オフシーズンの年末にお預かりし、DINO PAOLI社(イタリア)へ一括配送分のみ》

上記以外の単独での配送の場合は、日本からイタリアまでの輸出コスト実費が別途請求に成ります。